

Indoor Calibration Target



Jackson Pollock, *One: Number 31*, 1950

Instructions:

1. Print off this target. Color or black and white are both acceptable.
2. Switch your calibration mode to "Indoor Mode" (Having Trouble > Enable Indoor Mode > OK)
3. Point your sensor at the target. Move slowly, stopping to allow the sensor to gather more blue dots.